


MAXIMUM EFFICIENCY



I_a DEPENDS ON LOAD CONDITION

CONSTANT LOSSES = IRON + FRICTIONAL + SHUNT FIELD
LOSSES COPPER LOSS

VARIABLE LOSSES = ARMATURE + SERIES FIELD
COPPER LOSS COPPER LOSS

MAXIMUM EFFICIENCY OCCURS WHEN CONSTANT LOSS
IS EQUAL TO VARIABLE LOSS.

SHUNT MACHINE

$$\text{VARIABLE LOSS} = I_a^2 R_a$$

$$\text{CONSTANT LOSS} = \text{VARIABLE LOSS} = I_a^2 R_a$$

$$\text{TOTAL LOSSES} = \text{VARIABLE LOSS} + \text{CONSTANT LOSS}$$

$$= I_a^2 R_a + I_a^2 R_a = 2 I_a^2 R_a$$

ANT
 R_{sh}
INSTANT.

$$\text{MAXIMUM EFFICIENCY} = \frac{\text{OUT PUT power}}{\text{IN PUT power}} \times 100$$

$$= \frac{\text{OUT PUT power}}{\text{OUTPUT power} + \text{TOTAL LOSSES}} \times 100$$


$$\eta_{\max} = \frac{V_t I_L}{V_t I_L + 2 I_a^2 R_a} \times 100$$

Ex A 50 KW, 250V SHUNT GENERATOR HAS AN ARMATURE CIRCUIT RESISTANCE OF 0.05Ω, FIELD RESISTANCE OF 5Ω AND A MAXIMUM EFFICIENCY 91%. CALCULATE

- (a) TOTAL LOAD FOR WHICH THE EFFICIENCY IS APPROXIMATELY A MAXIMUM
 (b) STRAY POWER LOSS

$$\eta_{\max} = \frac{V_t I_L}{V_t I_L + 2 I_a^2 R_a} \times 100$$

$$91 = \frac{V_t I_L}{V_t I_L + 2 I_a^2 R_a} \times 100$$



$$q_1 = \frac{250 I_L}{250 I_L + 2 I_a^2 \times 0.05} \times 100$$

$$I_a = I_L + I_{sh}$$

$$I_{sh} = \frac{V_t}{R_{sh}} = \frac{250}{50} = 5 \text{ Amp}$$

$$I_a = I_L + s$$

$$0.91 = \frac{250 I_L}{250 I_L + 2 \times (I_L + s)^2 \times 0.05}$$

$$0.91 = \frac{250 I_L}{250 I_L + 0.1 (I_L^2 + 10 I_L + 2s)}$$

$$\frac{\frac{I_L + s}{I_L + s}}{\frac{I_L^2 + 5I_L + 2s}{I_L^2 + 10 I_L + 2s}}$$

$$0.91 = \frac{250 I_L}{250 I_L + 0.1 I_L^2 + I_L + 2s}$$

$$0.91 (250 I_L + 0.1 I_L^2 + I_L + 2s) = 250 I_L$$

$$227.5 I_L + 0.091 I_L^2 + 0.91 I_L + 2.275 = 250 I_L$$

$$0.091 I_L^2 - 21.59 I_L + 2.275 = 0$$

$$A x^2 + Bx + C = 0$$

$$x = \frac{-B \pm \sqrt{B^2 - 4AC}}{2A}$$

$$I_L = \frac{-(-21.59) \pm \sqrt{(-21.59)^2 - 4 \times 0.091 \times 2.275}}{2 \times 0.091}$$

$$= 247.2 \text{ Amp.}$$

$$\text{STRAY loss} = I_a^2 R_a - V_t \times I_{\text{field}}$$

$$I_a = I_b + I_{sh} = 247.2 + 5 = 252.2 \text{ Amp}$$

$$I_{\text{field}} = I_{sh} = 5 \text{ Amp}$$

$$\begin{aligned}\text{STRAY loss} &= I_a^2 R_a - V_t I_{sh} \\ &= (252.2)^2 \times 0.05 - 250 \times 5 \\ &= 1600 \text{ WATT}\end{aligned}$$

$$\text{STRAY LOSS} = I_a^2 R_a - V_t \times I_{\text{field}}$$

$$I_a = I_b + I_{sh} = 247.2 + 5 = 252.2 \text{ Amp}$$

$$I_{\text{field}} = I_{sh} = 5 \text{ Amp}$$

$$\begin{aligned}\text{STRAY LOSS} &= I_a^2 R_a - V_t I_{sh} \\ &= (252.2)^2 \times 0.05 - 250 \times 5 \\ &= 1800 \text{ WATT}\end{aligned}$$

MACHINE TEMPERATURE RISE

MACHINE TEMPERATURE RISE CAN BE MEASURED

BY

- (a) THERMOMETER
- (b) EMBEDDED THERMO COUPLE (OR) THERMISTOR
- (c) COMPUTATION FROM HOT AND COLD
RESISTANCE

$$\frac{R_F}{R_{RT}} = \frac{234.5 + T_F}{234.5 + T_{RT}}$$

R_F = FINAL RESISTANCE

R_{RT} = RESISTANCE AT ROOM TEMPERATURE

T_F = FINAL TEMPERATURE

T_{RT} = ROOM TEMPERATURE (25°C)

Ex

THE RESISTANCE OF AN ARMATURE WINDING AT 25°C WAS FOUND TO BE 0.26Ω . AFTER A HEAT RUN, IT BECOMES 0.296Ω . CALCULATE TEMPERATURE RISE OF THE WINDING.

$$T_{RT} = 25^{\circ}\text{C}, \quad R_{RT} = 0.26\Omega$$

$$R_F = 0.296\Omega$$

$$T_F = ?$$

$$\frac{R_F}{R_{RT}} = \frac{234.5 + T_F}{234.5 + T_{RT}}$$

$$\frac{0.296}{0.26} = \frac{234.5 + T_F}{234.5 + 25}$$

$$\frac{0.296}{0.26} (234.5 + 25) - 234.5 = T_F$$

$$T_F = 6^{\circ}\text{C}$$

$$\text{TEMPERATURE RISE} = T_F - T_{RT} = 61 - 25 = 36^{\circ}\text{C}$$

TO

ANALYSIS OF POWER LOSSES IN DC MACHINE

ROTATIONAL LOSSES

- (a) BEARING FRICTION
- (b) WIND FRICTION
- (c) BRUSH FRICTION ————— DEPENDS ON KIND OF BRUSH
- (d) HYSTERESIS
- (e) IRON EDDY CURRENT LOSSES

HYSTERESIS LOSS

- DEPENDS ON QUALITY OF IRON
- FREQUENCY OF AC CURRENT

$$f = \frac{PN}{120} \text{ Hz}$$

- FLUX DENSITY IN ARMATURE CORE
- MASS OF IRON

$$P_h = K_h f B^m \text{ WATT}$$

K_h = CONSTANT DEPENDING ON MATERIAL & UNIT USED


SH

f = FREQUENCY (Hz)


B = MAXIMUM FLUX DENSITY (T)

m = MASS OF CORE (kg)

EDDY CURRENT PATHS IN SOLID CORE



EDDY CURRENT PATHS IN LAMINATION



THE EDDY CURRENT LOSS DEPENDS ON

- FREQUENCY OF THE ALTERNATING CURRENT
(OR) FLUX IN ARMATURE CORE
- THE THICKNESS OF THE ARMATURE CORE
LAMINATION
- THE FLUX DENSITY IN THE CORE
- THE VOLUME OF THE IRON.

$$P_E = K_e f^2 t^2 B^2 V$$

WATT

P_E = EDDY CURRENT LOSS WATT

K_e = CONSTANT DEPENDING ON THE RESISTIVITY OF
THE IRON AND DIMENSIONS EMPLOYED FOR
THE FACTOR

f = FREQUENCY Hz

t = THICKNESS OF LAMINATION m

B = MAXIMUM FLUX DENSITY IN CORE T

V = VOLUME OF IRON IN CORE

$$P_h = K_h f^{1.6} B^m m \text{ WATT}$$

2USH


K_h = CONSTANT DEPENDING ON MATERIAL & UNIT USED

f = FREQUENCY (Hz)


B = MAXIMUM FLUX DENSITY (T)

m = MASS OF CORE (kg)

EDDY CURRENT PATHS IN SOLID CORE



EDDY CURRENT PATHS IN LAMINATION



THE EDDY CURRENT LOSS DEPENDS ON

- FREQUENCY OF THE ALTERNATING CURRENT
(OR) FLUX IN ARMATURE CORE
- THE THICKNESS OF THE ARMATURE CORE
LAMINATION
- THE FLUX DENSITY IN THE CORE
- THE VOLUME OF THE IRON.

$$P_E = K_e f^2 t^2 B^2 V$$

WATT

P_E = EDDY CURRENT LOSS WATT

K_e = CONSTANT DEPENDING ON THE RESISTIVITY OF
THE IRON AND DIMENSIONS EMPLOYED FOR
THE FACTOR

f = Frequency Hz

t = THICKNESS OF LAMINATION m

B = MAXIMUM FLUX DENSITY IN CORE T

V = VOLUME OF IRON IN CORE (m³)

E/T CALCULATE EASY CURRENT AND HYSTERESIS LOSSES FOR THE
GIVEN DC MACHINE

$$K_e = 3, \quad K_h = 2 \quad \text{FREQUENCY} = 60 \text{ Hz}$$

$$\text{THICKNESS OF LAMINATION} = 0.5 \text{ mm}$$

$$\text{CORE FLUX DENSITY} = 10 \text{ TESLA}$$

$$\text{VOLUME OF CORE} = 7 \text{ m}^3$$

$$\text{MASS OF CORE} = 50 \text{ kg}$$

1.6

$$P_h = K_h f B m$$

$$= 2 \times 60 \times (10)^{1.6} \times 50$$

$$= 120 \times 39.8 \times 50$$

$$= 238864 \text{ WATT}$$

$$= 238.86 \text{ kW}$$

$$\begin{aligned} P_e &= K_e f^2 \{ B^2 \} \\ &= 3 \times (60)^2 \times (0.5 \times 10^{-3})^2 \times 10^4 \times 7 \\ &= 3 \times 3600 \times 0.25 \times 10^6 \times 100 \times 7 \\ &= 1890000 \times 10^{-6} \\ &= 1.89 \text{ WATT} \end{aligned}$$

PERCENTAGE VOLTAGE REGULATION

WHEN THE LOAD IS APPLIED ON A SELF- EXCITED SHUNT GENERATOR
THE TERMINAL VOLTAGE WILL DROP DUE TO THREE EFFECTS. THESE
ARE

- (1) THE DROP IN THE RESISTANCE OF THE ARMATURE WINDING
WHICH IS TERMED $I_a R_a$ DROP
- (2) THE EFFECT OF THE ARMATURE FIELD ON THE MAIN FIELD
WHICH WILL DECREASE THE EFFECTIVE FLUX
- (3) THE RESULTANT DROP IN (1) & (2)

$$\text{PERCENTAGE REGULATION} = \frac{E_g - V_{FL}}{V_{FL}} \times 100$$

V_{FL} = FULL LOAD RATED VOLTAGE

E_g = NO LOAD OPEN CIRCUIT
(GENERATED) VOLTAGE

Pb

VFL OF A SHUNT GENERATOR IS 480 VOLT. WHAT IS PERCENTAGE
REGULATION IF THE OPEN CIRCUIT VOLTAGE IS 510V?

(a)

$$\begin{aligned}\% \text{ REGULATION} &= \frac{E_o - V_{FL}}{V_{FL}} \times 100 \\ &= \frac{510 - 480}{480} \times 100 \\ &= 6.85\%\end{aligned}$$

Pb

A 75 KW 500 VOLT GENERATOR HAS A VOLTAGE REGULATION
OF 4%. CALCULATE

(a) THE OPEN CIRCUIT VOLTAGE

(b) ASSUMING THE VOLTAGE VARIES UNIFORMLY BETWEEN
NO LOAD AND FULL LOAD CURRENT.

CALCULATE THE KW OUTPUT OF A TERMINAL VOLTAGE
OF 510.


STAGE

$$(a) \% R_{EG} = \frac{E_g - V_{FL}}{V_{FL}} \times 100$$

$$4 = \frac{E_g - 500}{500} \times 100$$

$$\frac{4 \times 500}{100} + 500 = E_g$$

$$E_g = 520V$$



$$\frac{V_1 - V_2}{V_1 - V} = \frac{I_2}{I_1}$$

$$\frac{520 - 510}{520 - 500} = \frac{I_{S10}}{I_{S20}}$$

V_1 = NO LOAD
VOLTAGE

V = FULL LOAD
VOLTAGE

V_2 = ANY VOLTAGE

$$\frac{I_0}{20} = \frac{I_{S10}}{I_{S20}}$$

Full load current \Rightarrow TERMINAL VOLTAGE
 $500V$

No load voltage $520V$

$= \frac{\text{Power}}{\text{TERMINAL VOLTAGE}}$

$= \frac{75 \times 10^3}{500}$


$I_{S20} = 150 \text{ Amp.}$

$$\frac{I_0}{20} = \frac{I_{S10}}{150}$$

$$I_{S10} = 150 \times \frac{10}{20} = 75 \text{ Amp.}$$

Output $= V \times I = 510 \times 75 = 38250W$
 $= 38.25 \text{ kW}$

LOADING A GENERATOR



$$E_g = V + I_a R_a$$

$$I_a = I_L + I_f$$

$$I_f = \frac{V}{R_f}$$

GENERATED VOLTAGE EQUATION

$$E_g = \frac{\phi Z N}{60} \times \frac{P}{a}$$

E_g = GENERATED VOLTAGE (V)

ϕ = FLUX (WB)

Z = NO. OF ARMATURE CONDUCTORS

N = SPEED (RPM)

P = NO. OF POLES

a = NO. OF ARMATURE PARALLEL PATHS

$$a = m \times p \quad LAP$$


$m = 1$ SIMPLEX

$= 2$ DUPLEX

$= 3$ TRIPLEX

$$a = m \times 2 \quad WAVE$$

LOADING A GENERATOR



$$E_g = V + I_a R_a$$

$$I_a = I_L + I_f$$

$$I_f = \frac{V}{R_f}$$

GENERATED VOLTAGE EQUATION

$$E_g = \frac{\phi Z N}{60} \times \frac{P}{a}$$

Eg = GENERATED VOLTAGE (V)

ϕ = Flux (Wb)

Z = NO. OF ARMATURE CONDUCTORS

N = SPEED (RPM)

P = NO. OF POLES

a = NO. OF ARMATURE PARALLEL PATHS

$$a = m \times p \quad LAP$$

m = 1 SIMPLEX

= 2 DUPLEX

= 3 TRIPLEX

$$a = m \times 2 \quad WAVE$$