


AC MACHINE — { 0043
0045

ROTATING FIELD DUE TO 3φ WINDING



F_a, F_b, F_c - STATOR FIELD DIRECTION
 FF - ROTOR FIELD DIRECTION

I_m = MAXIMUM CURRENT
 N = NUMBER OF TURNS

$$i_a = I_{m} \cos \omega t = \frac{I_m}{2} (e^{j\omega t} + e^{-j\omega t})$$

$$\omega = 2\pi f$$

$$\pi = 3.1416$$

f = FREQUENCY (HZ)

$$i_b = \frac{I_m}{2} (e^{j(\omega t - 2\pi/3)} + e^{-j(\omega t - 2\pi/3)})$$

$$i_c = \frac{I_m}{2} (e^{j(\omega t + 2\pi/3)} + e^{-j(\omega t + 2\pi/3)})$$

$$i_a = \frac{I_m N}{2} (e^{j\omega t} + e^{-j\omega t}) \times e^{j0}$$

$$i_b = \frac{I_m N}{2} (e^{j\omega t} + e^{-j(\omega t - 4\pi/3)})$$

$$F_c = \frac{I_m N}{2} (e^{j\omega t} + e^{-j(\omega t + 4\pi/3)})$$

$$F = \frac{3 I_m N}{2} e^{j\omega t}$$

ROTATIONAL FORCE PRODUCED BY 3 ϕ WINDING

I_m = MAXIMUM CURRENT

N = NUMBER OF TURNS



Position of Rotor	I_a	I_b	I_c
0	I_m	$-\frac{1}{2} I_m$	$-\frac{1}{2} I_m$
30°	$\frac{\sqrt{3}}{2} I_m$	0	$-\frac{\sqrt{3}}{2} I_m$
60°	$\frac{1}{2} I_m$	$\frac{1}{2} I_m$	$-I_m$
90°	0	$\frac{\sqrt{3}}{2} I_m$	$-\frac{\sqrt{3}}{2} I_m$

CONDITION

STATOR COILS ARE 120° APART


CURRENT FLOWS IN TO DOTS

THE CURRENTS IN a, b, c COILS ARE VARYING AS

ABOVE TABLE

THE ROTATING MAGNETIC FIELD IS PRODUCED

$$F = \frac{3 I_m N}{2} \text{ just } e$$



CONNECTION OF 3ϕ MACHINE

SPEED OF AC MACHINE

$$\text{SYNCHRONOUS SPEED} = \frac{120 f}{P}$$

N_s

N_s = SYNCHRONOUS SPEED

f = FREQUENCY OF SOURCE

P = NUMBER OF POLES


THE SPEED OF A ROTATING FIELD DEPENDS ON
THE FREQUENCY OF THE SOURCE AND NUMBER
OF POLES ON THE STATOR

PROBLEM

CALCULATE THE SYNCHRONOUS SPEED OF A 3 ϕ INDUCTION MOTOR HAVING 20 POLES WHEN IT IS CONNECTED TO A 50 HZ SOURCE.

$$N_s = \frac{120f}{P} = \frac{120 \times 50}{20} = 300 \text{ RPM}$$

6 poles




STATOR


POLES

FORMED
BY

STATOR WINDING




STARTING CHARACTERISTICS OF SCREWREL CAGE MOTOR



MOTOR STATOR
3φ WINDING

INTERACTION BETWEEN STATOR AND ROTOR FIELDS
BRING THE MOTOR TO SPEED UP.




SCREWREL CAGE
ROTOR

3φ WINDINGS AND

- WINDING MAY BE E
- WINDINGS ARE I
- THE COLLS MAY BE

SCREWREL CAGE INDUCTION MOTOR




IRREL CAGE MOTOR

3 CURRENT
SINE BARS

ROTOR MAGNETIC FIELD

AND ROTOR FIELDS
U.P.




SQUIRREL CAGE
ROTOR

3φ WINDINGS AND FIELD

- WINDING MAY BE EITHER ON THE STATOR (OR) ON THE ROTOR
- WINDINGS ARE 120 ELECTRICAL DEGREE APART.
- THE COILS MAY BE CONNECTED IN STAR OR DELTA


SQUIRREL CAGE INDUCTION MOTOR



STATOR
WINDING

TERMINAL BOX

WOUND ROTOR MOTOR




ROTOR FIELD
RHEOSTAT

ROTOR WINDING

SLIP RING

WOUND ROTOR





STATOR
WINDING

3φ
Supply

3φ MOTOR WINDING DESIGN

COIL SPAN




$$\text{COIL SPAN} = \frac{\text{NO OF SLOTS}}{\text{NO OF POLES}} = \frac{S}{P}$$

Pb DESIGN 3φ, 36 SLOTS, 4 POLES
WINDING.

$$\text{COIL SPAN} = \frac{\text{NO. OF SLOTS}}{\text{NO. OF POLES}} = \frac{36}{4} = 9$$

1 2 3 4 5 6



START

1 → 10

2 → 9

3 → 8


4 → 7

5 → 6

1 POLE

CONCENTRIC

$$\text{COIL SPAN} = \frac{\text{NO. OF SLOTS}}{\text{NO. OF POLES}} = \frac{36}{4} = 9 \quad \text{slot } 1 \rightarrow 10$$




START

END (6)

- 1 → 10
- 2 → 9
- 3 → 8
- 4 → 7
- 5 → 6


1 POLE

CONCENTRIC WINDING




- 1 → 6
- 2 → 7
- 3 → 8
- 4 → 9
- 5 → 10

LAP WINDING




- 1 → 6
- 2 → 7
- 3 → 8
- 4 → 9
- 5 → 10

LAP WINDING




PHASE (A)



EACH POLE =
COLL SPANS


$180 = 9$
 $120 =$

(B) PHASE




8 9 10

PHASE (A)




EACH POLE = 180°
 COIL SPAN 9 SLOTS = 180°
 $180^\circ = 9 \text{ SLOTS}$
 $225^\circ - ? = \frac{9 \times 120}{180} = 6 \text{ SLOTS}$

(B) PHASE



C PHASE

7+6 =



C PHASE

$7+6 = 13$

