


# % VOLTAGE REGULATION OF TRANSFORMER

$$\% \text{ VOLTAGE REGULATION} = \frac{\text{NO LOAD VOLTAGE} - \text{FULL LOAD VOLTAGE}}{\text{NO LOAD VOLTAGE}} \times 100$$



LAGGING P.F  $\Rightarrow$   $\% \text{ VOLTAGE REGULATION} = \frac{I_s' (R_{eq}' \cos\theta + X_{eq}' \sin\theta)}{V_p} \times 100$

LEADING P.F  $\Rightarrow$   $\% \text{ VOLTAGE REGULATION} = \frac{I_s' (R_{eq}' \cos\theta - X_{eq}' \sin\theta)}{V_p} \times 100$

↑  
POWER FACTOR

$$\% \text{ VOLTAGE REGULATION} = \frac{I_s R_{eq}}{V_P} \times 100 \cos\theta + \frac{I_s X_{eq}}{V_P} \times 100 \sin\theta$$

$$\% \text{ VOLTAGE REGULATION} = \% R_{eq} \cos\theta + \% X_{eq} \sin\theta \quad \leftarrow \text{LAGGING P.F}$$

$$\% \text{ VOLTAGE REGULATION} = \% R_{eq} \cos\theta - \% X_{eq} \sin\theta \quad \leftarrow \text{LEADING PF}$$

Pb ①

$\% R = 2$  ,  $\% X = 4$  FIND  $\% \text{ VOLTAGE REGULATION}$  AT  
0.8 PF LAGGING.

$$\% \text{ VOLTAGE REGULATION} = \% R \cos\theta + \% X \sin\theta$$

$$\cos\theta = 0.8 \rightarrow \theta = \cos^{-1} 0.8 = 36.8^\circ$$

$$\sin\theta = \sin 36.8 = 0.6$$

$$\begin{aligned} \% \text{ V REG} &= 2 \times 0.8 + 4 \times 0.6 \\ &= 1.6 + 2.4 \\ &= 4\% \end{aligned}$$

pb (2)


$N_p = 400, N_s = 80$

$R_p = 0.3 \Omega, R_s = 0.01 \Omega$   
 $X_p = 0.1 \Omega, X_s = 0.03 \Omega$   
 $V_p = 2200V, V_s = 440V$

FIND  $Z_{eq}'$ ,  $V_s'$

% REGULATION FOR 0.8 PF LAGGING  
 % REGULATION FOR 0.8 PF LEADING

(TRANSFORMER IS 100KVA, 1 $\phi$ )



% VOLTAGE REGULATION = 
$$\frac{I' (R_{eq} \cos \theta + X_{eq} \sin \theta)}{V_p} \times 100$$

$$I = \frac{KVA \times 10^3}{\text{PRIMARY VOLTAGE}} = \frac{100 \times 10^3}{2200} = 227.3 \text{ Amp}$$

$PF = \cos \theta$   
 $\theta = \cos^{-1} P.F$   
 $= \cos^{-1} 0.8$   
 $= 36.8$

$\sin \theta = \sin 36.8$   
 $= 0.6$

$$R_{eq} = R_p + \left(\frac{N_p}{N_s}\right)^2 R_s = 0.3 + \left(\frac{2200}{440}\right)^2 \times 0.01 = 0.3 + 25 \times 0.01 = 0.55 \Omega$$

$$X_{eq} = X_p + \left(\frac{N_p}{N_s}\right)^2 X_s = 0.1 + \left(\frac{2200}{440}\right)^2 \times 0.03 = 0.1 + 25 \times 0.03 = 0.85 \Omega$$

% VOLTAGE REGULATION =  $\frac{227.3 \left(0.55 \times 0.8 + 0.85 \times 0.6\right)}{2200} \times 100 = 9.8\%$   
 for 0.8 PF LAGGING

% VOLTAGE REGULATION =  $\frac{227.3 \left(0.55 \times 0.8 - 0.85 \times 0.6\right)}{2200} \times 100 = -0.72\%$   
 for 0.8 PF LEADING

$R_s = 0.01 \Omega$   
 $X_s = 0.03 \Omega$   
 $V_s = 440 V$

0.8 PF LAGGING  
 0.8 PF LEADING

$$R_{eq} = R_p + \left(\frac{NP}{N_s}\right)^2 R_s = 0.3 + \left(\frac{2200}{440}\right)^2 \times 0.01 = 0.3 + 25 \times 0.01 = 0.55 \Omega$$

$$X_{eq} = X_p + \left(\frac{NP}{N_s}\right)^2 X_s = 0.1 + \left(\frac{2200}{440}\right)^2 \times 0.03 = 0.1 + 25 \times 0.03 = 0.85 \Omega$$

% VOLTAGE REGULATION =  $\frac{227.3 (0.55 \times 0.8 + 0.85 \times 0.6)}{2200} \times 100 = 9.8 \%$   
 for 0.8 PF LAGGING

% VOLTAGE REGULATION =  $\frac{227.3 (0.55 \times 0.8 - 0.85 \times 0.6)}{2200} \times 100 = -0.72 \%$   
 for 0.8 PF LEADING

$PF = \cos \theta$   
 $\theta = \cos^{-1} PF$   
 $= \cos^{-1} 0.8$   
 $= 36.8$   
 $\sin \theta = \sin 36.8$   
 $= 0.6$


MAXIMUM REGULATION

% REG = %R cos $\theta$  + %X sin $\theta$

$\frac{d}{d\theta} \% REG = \frac{d}{d\theta} (\%R \cos\theta + \%X \sin\theta)$

$0 = -\%R \sin\theta + \%X \cos\theta$

MAXIMUM REGULATION



$$\left(\frac{2200}{440}\right)^2 \times 0.01 = 0.3 + 25 \times 0.01 = 0.55 \Omega$$

$$\left(\frac{2200}{440}\right)^2 \times 0.03 = 0.1 + 25 \times 0.03 = 0.85 \Omega$$

$$\frac{0.8 + 0.85 \times 0.6}{100} \times 100 = 9.8 \%$$

$$\frac{0.8 - 0.85 \times 0.6}{100} \times 100 = -0.72 \%$$

$$\frac{dR}{dx} = 0 \rightarrow \text{MAXIMUM POINT}$$



MAXIMUM  
REGULATION

$$\%R \sin \theta = \%X \cos \theta$$

$$\frac{\sin \theta}{\cos \theta} = \frac{\%X}{\%R}$$

$$\tan \theta = \frac{\%X}{\%R}$$

MAXIMUM  
REGULATION

Pb ' IF  $\%R = 3$ ,  $\%X = 5$ , FIND  $\%REG = ?$   
P.F LAGGING

$$\tan \theta = \frac{\%X}{\%R} = \frac{5}{3} = 1.667$$

$$\theta = \tan^{-1} 1.667 = 59.64$$


$$\%REG = \%R \cos \theta + \%X \sin \theta$$

$$= 3 \times \cos 59.64 + 5 \sin 59.64$$

$$= 3 \times 0.6 + 5 \times 0.8$$

$$= 5.8 \%$$

## TRANSFORMER LOSSES AND EFFICIENCY



$$\% \text{ EFFICIENCY} = \frac{\text{INPUT POWER} - (\text{CORE LOSS} + \text{WINDING LOSS})}{\text{INPUT POWER}} \times 100$$

IF TRANSFORMER IS SUPPLYING THE LOAD LESS THAN FULL LOAD

$$\text{LOAD RATIO} = L = \frac{\text{ANY LOAD (VA (OR) KVA)}}{\text{FULL LOAD (VA (OR) KVA)}}$$

$$\text{ANY LOAD OUTPUT} = L \times \text{FULL LOAD KVA} \times \text{P.F.} \\ (\text{KW})$$

$$\text{ANY LOAD COPPER LOSS} = L^2 \times \text{FULL LOAD COPPER LOSS}$$

Pb 1 $\phi$ , 500KVA TRANSFORMER 6600/440V

IRON LOSS = 2.9 kW, FULL LOAD COPPER LOSS = 4 kW

FIND (a) % EFFICIENCY AT FULL LOAD 0.8 PF LAGGING

(b) % EFFICIENCY AT  $\frac{1}{2}$  LOAD 0.8 PF LAGGING

(a)  $L = 1$  FULL LOAD

$$\text{OUTPUT} = L \times \frac{\text{FULL LOAD}}{\text{KVA}} \times \text{P.F.} \\ = 1 \times 500 \times 0.8 = 400 \text{ kW}$$

IRON LOSS = 2.9 kW

COPPER LOSS = 4 kW

$$\% \text{ EFFICIENCY} = \frac{\text{INPUT} - (\text{CORE LOSS} + \text{WINDING LOSS})}{\text{INPUT}} \times 100$$

(OR)

$$\% \text{ EFFICIENCY} = \frac{\text{OUTPUT}}{\text{OUTPUT} + \text{CORE LOSS} + \text{WINDING LOSS}} \times 100$$

$$= \frac{400}{400 + 2.9 + 4} \times 100$$

$$= 98.3\%$$

Full Load

(a)  $L = 1$  Full Load

$$\text{Output} = L \times \frac{\text{Full Load kVA}}{\text{kVA}} \times \text{P.F.}$$
$$= 1 \times 500 \times 0.8 = 400 \text{ kW}$$

IRON loss = 2.9 kW

COPPER loss = 4 kW

$$\% \text{ EFFICIENCY} = \frac{\text{INPUT} - (\text{CORE loss} + \text{WINDING loss})}{\text{INPUT}} \times 100$$

- (OR)

$$\% \text{ EFFICIENCY} = \frac{\text{OUTPUT}}{\text{OUTPUT} + \text{CORE loss} + \text{WINDING loss}} \times 100$$

$$= \frac{400}{400 + 2.9 + 4} \times 100$$

$$= 98.3\%$$

(b)  $\text{output} = L \times \text{FULL LOAD kVA} \times \text{P.F.}$

$$= \frac{1}{2} \times 500 \times 0.8$$

$$= 200 \text{ kW}$$

IRON loss = 2.9 kW

$$\frac{1}{2} \text{ LOAD COPPER loss} = \left(\frac{1}{2}\right)^2 \times 4 = 1 \text{ kW}$$

$$\% \text{ EFFICIENCY} = \frac{200}{200 + 2.9 + 1} \times 100$$

$$= 98\%$$

## MAXIMUM EFFICIENCY OF TRANSFORMER

MAXIMUM EFFICIENCY  $\rightarrow$  TOTAL IRON LOSS = TOTAL COPPER LOSS AT MAXIMUM EFFICIENCY LOAD

$$W_I = L_{\text{MAX}}^2 W_{\text{CFL}}$$

$W_I$  = IRON LOSS

$W_{\text{CFL}}$  = FULL LOAD COPPER LOSS

pb

FIND THE LOAD AT MAXIMUM EFFICIENCY OF THE FOLLOWING SINGLE PHASE TRANSFORMER

KVA = 1000, VOLTAGE RATIO = 6600 / 400 IRON LOSS = 4 KW

FULL LOAD COPPER LOSS = 6 KW.

MAXIMUM EFFICIENCY IS ACHIEVED AT 0.6 PF LAGGING.

AT MAXIMUM EFFICIENCY

$$W_I = L_{\text{MAX}}^2 W_{\text{CFL}}$$

$$4 = L_{\text{MAX}}^2 \times 6$$

$$L_{\text{MAX}} = \sqrt{\frac{4}{6}} = 0.816$$

$$\begin{aligned} \text{OUTPUT AT } L_{\text{MAX}} &= L_{\text{MAX}} \times \text{RATED KVA} \times \text{PF} \\ &= 0.816 \times 1000 \times 0.6 = 489.89 \text{ kW} \end{aligned}$$

$$W_I = 4 \text{ kW}$$

$$W_C \text{ AT MAX EFFCY} = L_{\text{MAX}}^2 W_C FL$$
$$= (0.816)^2 \times 6$$
$$= 3.99 \text{ kW}$$

$$\% \text{ EFFICIENCY} = \frac{\text{OUTPUT}}{\text{OUTPUT} + W_I + W_C L_{\text{MAX}}} \times 100$$
$$= \frac{489.89}{489.89 + 4 + 3.99} \times 100$$
$$= 98.3\%$$

