

# Transient Stability

---

- **The ability of the power system to remain in synchronism when subject to large disturbances**
  - ◆ Large power and voltage angle oscillations do not permit linearization of the generator swing equations
- **Lyapunov energy functions**
  - ◆ simplified energy method: the Equal Area Criterion
- **Time-domain methods**
  - ◆ numerical integration of the swing equations
  - ◆ Runge-Kutta numerical integration techniques

# Equal Area Criterion

---

- **Quickly predicts the stability after a major disturbance**
  - ◆ graphical interpretation of the energy stored in the rotating masses
  - ◆ method only applicable to a few special cases:
    - one machine connected to an infinite bus
    - two machines connected together
- **Method provides physical insight to the dynamic behavior of machines**
  - ◆ relates the power angle with the acceleration power

# Equal Area Criterion

---

- For a synchronous machine connected to an infinite bus

$$\frac{H}{\pi f_0} \frac{d^2 \delta}{dt^2} = P_m - P_e = P_{accel}$$

$$\frac{d^2 \delta}{dt^2} = \frac{\pi f_0}{H} (P_m - P_e) = \frac{\pi f_0}{H} \cdot P_{accel}$$

- The energy form of the swing equation is obtained by multiplying both sides by the system frequency (shaft rotational speed)

$$\left( 2 \frac{d\delta}{dt} \right) \left( \frac{d^2 \delta}{dt^2} \right) = \frac{\pi f_0}{H} (P_m - P_e) \left( 2 \frac{d\delta}{dt} \right)$$

# Equal Area Criterion

---

$$2\left(\frac{d^2\delta}{dt^2}\right)\left(\frac{d\delta}{dt}\right) = \frac{\pi f_0}{H}(P_m - P_e)\left(2\frac{d\delta}{dt}\right)$$

- The left hand side can be reworked as the derivative of the square of the system frequency (shaft speed)

$$\frac{d}{dt}\left[\left(\frac{d\delta}{dt}\right)^2\right] = \frac{2\pi f_0}{H}(P_m - P_e)\frac{d\delta}{dt}$$

$$d\left[\left(\frac{d\delta}{dt}\right)^2\right] = \frac{2\pi f_0}{H}(P_m - P_e)d\delta$$

# Equal Area Criterion

---

- Integrating both sides with respect to time,

$$\left(\frac{d\delta}{dt}\right)^2 = \frac{2\pi f_0}{H} \int_{\delta_0}^{\delta} (P_m - P_e) d\delta$$

$$\frac{d\delta}{dt} = \sqrt{\frac{2\pi f_0}{H} \int_{\delta_0}^{\delta} (P_m - P_e) d\delta}$$

- The equation gives the relative speed of the machine. For stability, the speed must go to zero over time

$$\left.\frac{d\delta}{dt}\right|_{t \rightarrow \infty} = 0$$

$$0 = \int_{\delta_0}^{\delta} (P_m - P_e) d\delta$$

# Equal Area Criterion

---

- **Consider a machine operating at equilibrium**
  - ◆ the power angle,  $\delta = \delta_0$
  - ◆ the electrical load,  $P_{e0} = P_{m0}$
- **Consider a sudden increase in the mechanical power input**
  - ◆  $P_{m1} > P_{e0}$  ; the acceleration power is positive
  - ◆ excess energy is stored in the rotor and the power frequency increases, driving the relative power angle larger over time

$$U_{Potential} = \int_{\delta_0}^{\delta_1} (P_{m1} - P_e) d\delta > 0$$

$$\frac{d\delta}{dt} = \omega = \sqrt{\frac{2\pi f_0}{H} \int_{\delta_0}^{\delta} (P_m - P_e) d\delta} > 0$$

# Equal Area Criterion

---

- ◆ with increase in the power angle,  $\delta$ , the electrical power increases


$$P_e = P_{\max} \sin \delta$$

- ◆ when  $\delta = \delta_1$ , the electrical power equals the mechanical power,  $P_{m1}$
- ◆ acceleration power is zero, but the rotor is running above synchronous speed, hence the power angle,  $\delta$ , continues to increase
- ◆ now  $P_{m1} < P_e$ ; the acceleration power is negative (deceleration), causing the rotor to decelerate to synchronous speed at  $\delta = \delta_{\max}$
- ◆ an equal amount of energy must be given up by the rotating masses

$$U_{\text{Potential}} = \int_{\delta_0}^{\delta_1} (P_{m1} - P_e) d\delta - \int_{\delta_1}^{\delta_{\max}} (P_{m1} - P_e) d\delta = 0$$

# Equal Area Criterion

---



Power Systems I



# Equal Area Criterion

---

- The result is that the rotor swings to a maximum angle
  - ◆ at which point the acceleration energy area and the deceleration energy area are equal

$$\int_{\delta_0}^{\delta_1} (P_{m1} - P_e) d\delta = \mathbf{area\ } abc = \mathbf{area\ } A_1$$


$$\int_{\delta_1}^{\delta_{\max}} (P_{m1} - P_e) d\delta = \mathbf{area\ } bde = \mathbf{area\ } A_2$$

$$|\mathbf{area\ } A_1| = |\mathbf{area\ } A_2|$$

- ◆ this is known as the equal area criterion
- ◆ the rotor angle will oscillate back and forth between  $\delta$  and  $\delta_{\max}$  at its natural frequency

# Equal Area Criterion - $\Delta P$ mechanical

---



# Equal Area Criterion - $\Delta P$ mechanical

---

$$P_{m1}(\delta_1 - \delta_0) - \int_{\delta_0}^{\delta_1} P_{\max} \sin \delta \, d\delta = \int_{\delta_1}^{\delta_{\max}} P_{\max} \sin \delta \, d\delta - P_{m1}(\delta_{\max} - \delta_1)$$

$$P_{m1}(\delta_{\max} - \delta_0) = P_{\max}(\cos \delta_0 - \cos \delta_{\max})$$

$$P_{m1} = P_{\max} \sin \delta_{\max}$$


$$(\delta_{\max} - \delta_0) \sin \delta_{\max} = \cos \delta_0 - \cos \delta_{\max}$$

$$\rightarrow P_{m1} = P_{\max} \sin \delta_1$$

Function is nonlinear in  $\delta_{\max}$   
Solve using Newton-Raphson


# 3-Phase Fault

---



# Equal Area Criterion - 3 phase fault

---



## Equal Area Criterion - 3 phase fault


---

$$\int_{\delta_0}^{\delta_c} P_m d\delta = \int_{\delta_c}^{\delta_{\max}} (P_{\max} \sin \delta - P_m) d\delta$$

$$P_m (\delta_c - \delta_0) = P_{\max} (\cos \delta_c - \cos \delta_{\max}) - P_m (\delta_{\max} - \delta_c)$$

$$\cos \delta_c = \frac{P_m}{P_{\max}} (\delta_{\max} - \delta_c) + \cos \delta_{\max}$$

# Critical Clearing Time



# Critical Clearing Time

---

$$\frac{H}{\pi f_0} \frac{d^2 \delta}{dt^2} = P_m - P_e = P_m \leftarrow P_e = 0$$

$$\frac{d^2 \delta}{dt^2} = \frac{\pi f_0}{H} P_m$$

$$\frac{d\delta}{dt} = \frac{\pi f_0}{H} P_m \int_0^t dt = \frac{\pi f_0}{H} P_m t$$


$$\delta = \frac{\pi f_0}{2H} P_m t^2 + \delta_0$$

$$t_c = \sqrt{\frac{2H(\delta_c - \delta_0)}{\pi f_0 P_m}}$$




# 3-Phase Fault

---




# Equal Area Criterion

---



# Critical Clearing Time



# Critical Clearing Time

---

$$P_m(\delta_c - \delta_0) - \int_{\delta_0}^{\delta_c} P_{2\max} \sin \delta d\delta = \int_{\delta_c}^{\delta_{\max}} P_{3\max} \sin \delta d\delta - P_m(\delta_{\max} - \delta_c)$$
$$\cos \delta_c = \frac{P_m(\delta_{\max} - \delta_c) + P_{3\max} \cos \delta_{\max} - P_{2\max} \cos \delta_0}{P_{3\max} - P_{2\max}}$$