

Steady State Stability

- The ability of the power system to remain in synchronism when subject to small disturbances
- Stability is assured if the system returns to its original operating state (voltage magnitude and angle profile)
- The behavior can be determined with a linear system model
- **Assumption:**
 - ◆ the automatic controls are not active
 - ◆ the power shift is not large
 - ◆ the voltage angles changes are small

Steady State Stability

- **Swing Equation**

$$\frac{H_i}{\pi f_0} \frac{d^2 \delta_i}{dt^2} = P_{mi} - P_{max} \sin \delta$$

- **Small disturbance modeling**

$$\delta = \delta_0 + \Delta\delta \quad \text{Consider a small deviation}$$

$$\frac{H}{\pi f_0} \frac{d^2 (\delta_0 + \Delta\delta)}{dt^2} = P_m - P_{max} \sin(\delta_0 + \Delta\delta)$$

$$\frac{H}{\pi f_0} \frac{d^2 \delta_0}{dt^2} + \frac{H}{\pi f_0} \frac{d^2 \Delta\delta}{dt^2} = P_m - P_{max} [\sin \delta_0 \cos \Delta\delta + \cos \delta_0 \sin \Delta\delta]$$

Steady State Stability

- **Simplification of the swing equation**

$$\frac{H}{\pi f_0} \frac{d^2 \delta_0}{dt^2} + \frac{H}{\pi f_0} \frac{d^2 \Delta \delta}{dt^2} = P_m - P_{max} [\sin \delta_0 \cos \Delta \delta + \cos \delta_0 \sin \Delta \delta]$$

Substitute the following approximations

$$\Delta \delta \ll \delta \quad \cos \Delta \delta \approx 1 \quad \sin \Delta \delta \approx \Delta \delta$$

$$\frac{H}{\pi f_0} \frac{d^2 \delta_0}{dt^2} + \frac{H}{\pi f_0} \frac{d^2 \Delta \delta}{dt^2} = P_m - P_{max} \sin \delta_0 - P_{max} \cos \delta_0 \cdot \Delta \delta$$

Group steady state and transient terms

$$\frac{H}{\pi f_0} \frac{d^2 \delta_0}{dt^2} - P_m + P_{max} \sin \delta_0 = -\frac{H}{\pi f_0} \frac{d^2 \Delta \delta}{dt^2} - P_{max} \cos \delta_0 \cdot \Delta \delta$$

Steady State Stability

- **Simplification of the swing equation**

$$\frac{H}{\pi f_0} \frac{d^2 \delta_0}{dt^2} - P_m + P_{max} \sin \delta_0 = -\frac{H}{\pi f_0} \frac{d^2 \Delta \delta}{dt^2} - P_{max} \cos \delta_0 \cdot \Delta \delta$$

$$0 = \frac{H}{\pi f_0} \frac{d^2 \Delta \delta}{dt^2} + P_{max} \cos \delta_0 \cdot \Delta \delta$$

Steady state term is equal to zero

$$\left. \frac{dP_e}{d\delta} \right|_{\delta_0} = \left. \frac{d}{d\delta} P_{max} \sin \delta \right|_{\delta_0} = P_{max} \cos \delta_0 = P_s$$

$$\frac{H}{\pi f_0} \frac{d^2 \Delta \delta}{dt^2} + P_s \cdot \Delta \delta = 0 \quad \text{Second order equation.}$$

The solution depends on the roots of the characteristic equation


Stability

- **Stability Assessment**

- ◆ When P_s is negative, one root is in the right-half s -plane, and the response is exponentially increasing and stability is lost
- ◆ When P_s is positive, both roots are on the $j\omega$ axis, and the motion is oscillatory and undamped, the natural frequency is:

$$s^2 = -\frac{\pi f_0}{H} P_s$$

$$\omega_n = \sqrt{\frac{\pi f_0}{H} P_s}$$



Damping Torque

$$P_D = D \frac{d\delta}{dt} \quad \text{Damping force is due to air-gap interaction}$$

$$\frac{H}{\pi f_0} \frac{d^2 \Delta \delta}{dt^2} + D \frac{d\Delta \delta}{dt} + P_S \Delta \delta = 0$$

$$\frac{d^2 \Delta \delta}{dt^2} + \frac{\pi f_0}{H} D \frac{d\Delta \delta}{dt} + \frac{\pi f_0}{H} P_S \Delta \delta = 0$$

$$\frac{d^2 \Delta \delta}{dt^2} + 2\zeta \omega_n \frac{d\Delta \delta}{dt} + \omega_n^2 \Delta \delta = 0$$

$$\zeta = \frac{D}{2} \sqrt{\frac{\pi f_0}{H P_S}}$$

Characteristic Equation

$$s^2 + 2\zeta\omega_n s + \omega_n^2 = 0$$

$$\zeta = \frac{D}{2} \sqrt{\frac{\pi f_0}{H P_S}} < 1 \quad \text{for normal operation conditions}$$

$$s_1, s_2 = -\zeta\omega_n \pm j\omega_n \sqrt{1 - \zeta^2} \quad \text{complex roots}$$

$$\omega_d = \omega_n \sqrt{1 - \zeta^2} \quad \text{the damped frequency of oscillation}$$

Laplace Transform Analysis

$$x_1 = \Delta\delta, \quad x_2 = \frac{d\Delta\delta}{dt}$$

$$\begin{bmatrix} \dot{x}_1 \\ \dot{x}_2 \end{bmatrix} = \begin{bmatrix} 0 & 1 \\ -\omega_n^2 & -2\zeta\omega_n \end{bmatrix} \begin{bmatrix} x_1 \\ x_2 \end{bmatrix} = \dot{\mathbf{x}} = \mathbf{A}\mathbf{x}$$

$$\mathcal{L}\{\dot{\mathbf{x}} = \mathbf{A}\mathbf{x}\} \rightarrow s\mathbf{X}(s) - \mathbf{x}(0) = \mathbf{A}\mathbf{X}(s)$$

$$\mathbf{X}(s) = (s\mathbf{I} - \mathbf{A})^{-1} \mathbf{x}(0)$$

$$(s\mathbf{I} - \mathbf{A}) = \begin{bmatrix} s & -1 \\ \omega_n^2 & s + 2\zeta\omega_n \end{bmatrix}$$

$$\mathbf{X}(s) = \frac{\begin{bmatrix} s + 2\zeta\omega_n & 1 \\ -\omega_n^2 & s \end{bmatrix}}{s^2 + 2\zeta\omega_n s + \omega_n^2} \mathbf{x}(0)$$

Laplace Transform Analysis

$$\Delta\delta(s) = \frac{(s + 2\zeta\omega_n)\Delta\delta_0}{s^2 + 2\zeta\omega_n s + \omega_n^2}$$

$$\Delta\omega(s) = \frac{\omega_n^2 \Delta\delta_0}{s^2 + 2\zeta\omega_n s + \omega_n^2}$$

$$\Delta\delta(t) = \frac{\Delta\delta_0}{\sqrt{1-\zeta^2}} e^{-\zeta\omega_n t} \sin(\omega_d t + \theta), \quad \theta = \cos^{-1} \zeta$$


$$\Delta\omega(t) = -\frac{\omega_n \Delta\delta_0}{\sqrt{1-\zeta^2}} e^{-\zeta\omega_n t} \sin(\omega_d t)$$

$$\delta(t) = \delta_0 + \Delta\delta(t), \quad \omega(t) = \omega_0 + \Delta\omega(t)$$

Example

- A 60 Hz synchronous generator having inertia constant $H = 9.94$ MJ/MVA and a transient reactance $X'_d = 0.3$ pu is connected to an infinite bus through the following network. The generator is delivering 0.6 pu real power at 0.8 power factor lagging to the infinite bus at a voltage of 1 pu. Assume the damping power coefficient is $D = 0.138$ pu. Consider a small disturbance of 10° or 0.1745 radians. Obtain equations of rotor angle and generator frequency motion.

Example



Example

